


FIG. 1






P5878a, Serial No.: 10/002,033  
Customer No. 20178

2/7

FIG. 2





P5878a, Serial No.: 10/002,033  
Customer No. 20178

3/7

FIG. 3

PC MATERIAL  
 $B_m = 0.2T$   
 $f = 8Hz$





FIG. 4

PC MATERIAL  
 $B_m = 0.2T$   
 $f = 8Hz$






P5878a, Serial No.: 10/002,033  
Customer No. 20178

4/7

FIG. 5





P5878a, Serial No.: 10/002,033  
Customer No. 20178

5/7

FIG. 6

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 50Hz$





FIG. 7

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 50Hz$





P5878a, Serial No.: 10/002,033  
Customer No. 20178

6/7

FIG. 8

PB MATERIAL  
 $B_m = 0.9T$   
 $f = 50\text{Hz}$





FIG. 9

PD MATERIAL  
 $B_m = 0.9T$   
 $f = 50\text{Hz}$





P5878a, Serial No.: 10/002,033  
Customer No. 20178

7/7

FIG.10

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 100\text{Hz}$

